

# Portland Subarea 1: Northwestern Residential

## Recommendations

- Increase owner-occupancy
- Rehab Northwest area
- Highlight and connect access to river walk
- Assess the area to map repair needs
- Improve access to Lannan Park
- Improve fencing around I-64
- Alley maintenance (N. 26th St.)
- Analyze EZ zoning for appropriateness
- Develop signage for parks and river walk
- Consider down zoning M2
- Repair side walks
- Preserve historic alleys



UPGRADE FENCING AT I-64

IMPROVE ACCESS TO LANNAN PARK

UPGRADE  
PEDESTRIAN  
OVERPASS

INVENTORY AREA FOR  
REHABILITATION NEEDS

INCREASE PROGRAMMING  
IN PORTLAND PARK

ALLEY SURVEYS  
• illegal dumping activity  
• historic preservation